

Threshold

Sets the level at which reduction begins




Ratio

Changes the amount of gain reduction above the set threshold level



Attack Time

Changes the time delay before compression begins



Release Time

Changes the time taken for the gain return to 0 after the compressor disengages



IN

Engages the Compressor



Make-Up Gain

Gain make-up after compression




SC HPF

Applies a HPF at 250 Hz to the VCA side chain signal



Level Meter

8 segment LED meters for monitoring output level



FF/FB

When engaged, changes the VCA detection from Feed-forward to Feed-back



RMS/Peak

When engaged, changes the VCA detection from RMS (average) to a Peak & RMS hybrid



Gain Reduction Meter

8 segment LED Meter for monitoring gain reduction



R