
## TONE WORKSTATION CONTROLS



## **EFFECT TYPE:**

4 Effects, Red Dirt Overdrive, 1962 Overdrive, Katana Clean Boost, Compressor w/ Blend

## Power Requirement:

9VDC Center Negative, 20mA+ Power Supply Required.

## Input/Output: Mono Instrument In, Mono Instrument Output

